


CS4000 COMPUTER PORT CONNECTION

Pin	Signal	Description	9-Pin Serial Connector
A	RXD IN	Receive Data In	Pin 3
B	SIGNAL COMMON	Signal Common	Pin 5
C	SHIELD	Shield	N/C
D	DCD IN	Data Carrier Detect In	N/C
E	TXD OUT	Transmit Data Out	Pin 2
F	DSR IN	Data Set Ready In	N/C
G	DTR OUT	Data Terminal Ready Out	N/C
H	CTS IN	Clear To Send In	Pin 7
J	RTS OUT	Request To Send Out	Pin 8
K	RI IN	Ring Indicator In	N/C



COMPUTER CONNECTOR



PRINTER CONNECTOR

CS4000 PRINTER PORT CONNECTION

Pin	Signal	Description	9-Pin Serial Connector
A	TXD OUT	Data Transmit Out	Pin 2
B	SIGNAL COMMON	Signal Common	Pin 5
C	CTS IN	Clear To Send In	Pin 4
D	N/C	No Connect	N/C
E	SHIELD	Shield	N/C